## **Clean Earth Sampling Protocol** Southern Florida

Vousile Harver 10X Vousile Harver 10X Vousile Harver 10X Shanne Har							
METHODS (1)	FREQUENCY	FLO-PRO	9020 or 9023 Number of C	6000/7000 Composite Samples	1311/6010 (Except VOHs - G	8082A rab Samples)	8260B or 8021
Gas and Diesel	Less than 140 Tons	1		1	(2)		1
	140 to 699 Tons	3		3	(2)		3
	700 to 1399 Tons	5		5	(2)		5
	Every Additional 700 Tons Thereafter	1		1	(2)		1
Limit (mg/kg)				0.5 mg/kg Detection Limit			
Used Hydraulic Oil, Used Oil, Mineral Oil	Less than 140 Tons	1	1	1	(2)	1	1
	140 to 699 Tons	3	3	3	(2)	3	3
	700 to 1399 Tons	5	5	5	(2)	5	5
	Every Additional 700 Tons Thereafter	1	1	1	(2)	1	1
Limit (mg/kg)			1,000	0.5 mg/kg Detection Limit		50 (Detection Limit of 0.02 ppm)	

(1) The methods provided are standard EPA methods. The method revisions are subject to change and the most current method should always be utilized by the laboratory.
(2) TCLP may be required based on the Total Metals results.

NOTE - Based on current and historical site usage, additional analysis may be requested.